NTSB Identification: NYC76AN122

14 CFR Part 135 Nonscheduled operation of BAR HARBOR AIR Aircraft: BEECH 99, registration: N200WP

FILE	DATE	LOCATION	AIRCRAFT DATA		F	S M/	'N	PURPOSE		PILOT DATA
3-3176	TIME - 06		N200WP DAMAGE-DESTROYED	PX-	0 0	0 0	1 0			
	NAME OF AIRPORT - BAR HARBOR									
			INTENDED DESTINATION							
	BANGOR,ME ELLSWORTH,ME TYPE OF ACCIDENT				ь	IIACE	. 01	ODEDATION		
	COLLISION WITH GROUND/WATER: CONTROLLED				PHASE OF OPERATION					
	PROBABLE CAUSE(S)									
	PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.									
	PILOT IN COMMAND - IMPROPER IFR OPERATION									
	FACTOR(S)									
	WEATHER - LOW CEILING									
	WEATHER - RAIN									
	WEATHER - FOG									
	WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE									
	WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT SKY CONDITION				_		NC.	AT ACCIDENT SI	TE	
	OVERCAST				C	66 61LT		AT ACCIDENT 31	.16	
	VISIBILITY AT ACCIDENT SITE				P		-	ATION AT ACCID	ENT STTE	
	2 MILES OR LESS					RAI		ATTON AT ACCID	LIVI SIIL	
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE				W			OCITY-KNOTS		
	FOG					CAL	.M			
	TYPE OF WEATHER CONDITIONS				Т	YPE	OF	FLIGHT PLAN		
	BELOW MINIMUMS					IFR				
	REMARKS-	REMARKS- FLEW INTO 220 FT HILL, LOCALIZER APPROACH, ALTIMETER TESTED OK AFTER CRASH.								

Full narrative is not available