

## NTSB Identification: IAD77FID03

14 CFR Part 91 General Aviation  
 Aircraft: CESSNA 401, registration: N2WP

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-3968	76/10/24	HOT SPRINGS,VA	CESSNA 401 TIME - 0805 N2WP DAMAGE-DESTROYED	CR- 0 0 2 PX- 0 0 4 OT- 0 0 0	NONCOMMERCIAL CORP/EXEC		COMMERCIAL, AGE 46, 6400 TOTAL HOURS, 1000 IN TYPE, INSTRUMENT RATED.	
NAME OF AIRPORT - INGALS FIELD								
DEPARTURE POINT			INTENDED DESTINATION					
COLUMBIA,SC			HOT SPRINGS,VA					
TYPE OF ACCIDENT			PHASE OF OPERATION					
COLLIDED WITH: TREES			LANDING: FINAL APPROACH					
PROBABLE CAUSE(S)								
PILOT IN COMMAND - IMPROPER IFR OPERATION								
FACTOR(S)								
WEATHER - LOW CEILING								
WEATHER - RAIN								
WEATHER - FOG								
WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, IN PERSON								
WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT								
SKY CONDITION			CEILING AT ACCIDENT SITE					
PARTIAL OBSCURATION			300					
VISIBILITY AT ACCIDENT SITE			PRECIPITATION AT ACCIDENT SITE					
3 MILES OR LESS			RAIN					
OBSTRUCTIONS TO VISION AT ACCIDENT SITE			RELATIVE BEARING OF WIND					
FOG			LEFT CROSS WIND 248-292 DEGREES					
TEMPERATURE-F			WIND DIRECTION-DEGREES					
38			180					
WIND VELOCITY-KNOTS			TYPE OF WEATHER CONDITIONS					
10			IFR					
TYPE OF FLIGHT PLAN								
IFR								
FIRE AFTER IMPACT								
REMARKS- DSCND BELOW DH.								

Full narrative is not available