NTSB Identification: IAD77FA039

14 CFR Part 91 General Aviation Aircraft: PIPER PA-31, registration: N7439L

FILE	DATE	LOCATION	AIRCRAFT DATA					FLIGHT PURPOSE	PILOT DATA
3-1763	TIME - 06:	15	N7439L DAMAGE-DESTROYED	PX-	2	0	0	NONCOMMERCIAL CORP/EXEC	COMMERCIAL, FL.INSTR., AGE 55, 18000 TOTAL HOURS, 1000 IN TYPE, INSTRUMENT RATED.
	NAME OF AIRPORT - MCDONALD FIELD								
			INTENDED DESTINATION						
	TAPLIN,WV AMBLER,PA								
	TYPE OF ACCIDENT			PHASE OF OPERATION					
	COLLISION WITH GROUND/WATER: CONTROLLED					Ι	N F	LIGHT: CLIMB TO CRUISE	
	PROBABLE CAUSE(S)								
	PILOT IN COMMAND - INITIATED FLIGHT IN ADVERSE WEATHER CONDITIONS								
	FACTOR(S)								
	WEATHER - FOG WEATHER BRIEFING - NO RECORD OF BRIEFING RECEIVED								
	WEATHER BRIEFING - NO RECORD OF BRIEFING RECEIVED WEATHER FORECAST - UNKNOWN/NOT REPORTED								
	SKY CONDITION			CEILING AT ACCIDENT SITE					
	OBSCURATION			0					
	VISIBILITY AT ACCIDENT SITE			PRECIPITATION AT ACCIDENT SITE					
	1/4 MILE OR LESS					NO		TATION AN ACCIDENT SITE	
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE				Т			WEATHER CONDITIONS	
	FOG					IF	R		
	TYPE OF FLIGHT PLAN								
	NONE								
	FIRE AFTI	ER IMPACT							
	REMARKS- (CRASHED APRX 1/2MI	EAST OF FIELD.						

Full narrative is not available