## NTSB Identification: MIA78FA027

14 CFR Part 135 Scheduled operation of AERO VIRGIN IS Aircraft: DOUGLAS DC-3, registration: N15598

FILE	DATE LOCAT	ION AIRCRAFT DATA		F	S M	/N	FLIGHT PURPOSE	PILOT DATA	
3-1291	78/1/2 NR.RIO GRANI TIME - 0800	DE, PR DOUGLAS DC-3		0	0	3		AIRLINE TRANSPORT, AGE	
	11ME - 0800						AIR TAXI-PASSG S-D		
	DEPARTURE POINT	INTENDED DESTINATION							
	ST.THOMAS,VI	SAN JUAN,PR							
	TYPE OF ACCIDENT			Р	HAS	E 0	F OPERATION		
	ENGINE FAILURE OR MALFUNCTION						LIGHT: NORMAL CRUISE		
	DITCHING			LANDING: LEVEL OFF/TOUCHDOWN					
	PROBABLE CAUSE(S)								
	PILOT IN COMMAND - MISMANAGEMENT OF FUEL								
	MISCELLANEOUS ACTS,CONDITIONS - INATTENTIVE TO FUEL SUPPLY								
	MISCELLANEOUS ACTS, CONDITIONS - FUEL STARVATION								
	PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.								
	MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES								
	FACTOR(S)								
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING								
	PERSONNEL - OPERATIONAL SUPERVISORY PERSONNEL: INADEQUATE SUPERVISION OF FLIGHT CREW PERSONNEL - MAINTENANCE.SERVICING.INSPECTION: INADEQUATE INSPECTION OF AIRCRAFT (MAINTENANCE PERSONNEL)								
	PERSONNEL - MAINTENANCE, SERVICING, INSPECTION. INAUGUATE INSPECTION OF AIRCRAFT (MAINTENANCE PERSONNEL) MISCELLANEOUS ACTS.CONDITIONS - CHECKLIST-FAILED TO USE								
	MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO REST IN WATER								
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES								
	EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER								
	REMARKS- BOTH FUEL SELECTORS R MAIN. EMPTY. FUEL AVBL L TA								

Full narrative is not available