

# NTSB Identification: CHI78FA001

14 CFR Part 135 Scheduled operation of BLACKHAWK AIRW  
 Aircraft: BEECH E18S, registration: N5601D

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-4251	77/10/1 TIME - 0456	NR.PLYMOUTH,IN	BEECH E18S N5601D DAMAGE-DESTROYED	CR- 0 1 0 PX- 0 0 0 OT- 0 0 0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-CARGO S-D	AIRLINE TRANSPORT, AGE 45, 13676 TOTAL HOURS, 2355 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - PLYMOUTH MUNI DEPARTURE POINT DAYTON,OH INTENDED DESTINATION CHICAGO,IL TYPE OF ACCIDENT PROPELLER/ROTOR FAILURE: PROPELLER ENGINE TEARAWAY PHASE OF OPERATION IN FLIGHT: NORMAL CRUISE PROBABLE CAUSE(S) IN FLIGHT: NORMAL CRUISE POWERPLANT - PROPELLER AND ACCESSORIES: BLADES MISCELLANEOUS ACTS,CONDITIONS - NICKED MISCELLANEOUS ACTS,CONDITIONS - FATIGUE FRACTURE MISCELLANEOUS ACTS,CONDITIONS - VIBRATION,EXCESSIVE FACTOR(S) MISCELLANEOUS ACTS,CONDITIONS - SEPARATION IN FLIGHT REMARKS- ACFT DESTROYED DRG FORCED LDG.						

Full narrative is not available