

# NTSB Identification: DEN78FA046

14 CFR Part 91 General Aviation  
Aircraft: PIPER PA-31T, registration: N176CC

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3057	78/6/5	NR. LAMAR, CO	PIPER PA-31T	CR- 1 0 0	NONCOMMERCIAL	PRIVATE, AGE 46, 3000
	TIME - 2140		N176CC	PX- 3 0 0	PLEASURE/PERSONAL TRANSP	TOTAL HOURS, 100 IN TYPE,
			DAMAGE-DESTROYED	OT- 0 0 0		INSTRUMENT RATED.
		NAME OF AIRPORT - LAMAR MUNI				
		DEPARTURE POINT	INTENDED DESTINATION			
		LAMAR, CO	FT. COLLINS, CO			
		TYPE OF ACCIDENT		PHASE OF OPERATION		
		COLLISION WITH GROUND/WATER: CONTROLLED		IN FLIGHT: CLIMB TO CRUISE		
		PROBABLE CAUSE(S)				
		PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING				
		PILOT IN COMMAND - DIVERTED ATTENTION FROM OPERATION OF AIRCRAFT				
		MISCELLANEOUS ACTS, CONDITIONS - PILOT FATIGUE				
		FIRE AFTER IMPACT				
		REMARKS- TWO LARGE DOGS & ONE CAT IN ACFT UNRESTRAINED. PLT/MD FLEW APRX 6HRS & PERFORMED 2 OPNS DAY OF ACDT				

Full narrative is not available