

# NTSB Identification: NYC79FA017

14 CFR Part 91 General Aviation  
Aircraft: AEROSTAR 600, registration: N8022J

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2866	79/1/11 TIME - 1110	TEMPLETON,MA	AEROSTAR 600 N8022J DAMAGE-DESTROYED	CR- 1 0 0 PX- 1 0 0 OT- 3 0 0	NONCOMMERCIAL CORP/EXEC	COMMERCIAL, FL.INSTR., AGE 23, 1600 TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED.

NAME OF AIRPORT - GARDNER MUNI  
DEPARTURE POINT INTENDED DESTINATION  
BOSTON,MA SYRACUSE,NY  
TYPE OF ACCIDENT PHASE OF OPERATION  
COLLISION WITH AIRCRAFT: BOTH IN FLIGHT IN FLIGHT: NORMAL CRUISE  
PROBABLE CAUSE(S)  
PILOT IN COMMAND - FAILED TO SEE AND AVOID OTHER AIRCRAFT  
PERSONNEL - MISCELLANEOUS-PERSONNEL: PILOT OF OTHER AIRCRAFT  
SPECIAL DATA  
SEGMENTS OF AVIATION INVOLVED - SMALL US GEN.AV.-SMALL US GEN.AV.  
CONTROLLING AGENCY - NO CONTROL EVASIVE ACTION TAKEN - UNKNOWN/NOT REPORTED  
ANTI-COLLISION LIGHTS - INSTALLED,OPERATION UNKNOWN  
FIRE AFTER IMPACT

Full narrative is not available