

NTSB Identification: MIA78DLD76

14 CFR Part 91 General Aviation
Aircraft: BEECH G18S, registration: N948Q

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT	PILOT DATA	
				F	S	M/N	PURPOSE		
3-4442	78/9/12	NR.NNASSAU,BAHAMAS	BEECH G18S	CR-	0	0	1	NONCOMMERCIAL	COMMERCIAL, AGE 44, 5100
	TIME - 2230		N948Q	PX-	0	0	1	PLEASURE/PERSONAL TRANSP	TOTAL HOURS, 46 IN TYPE,
			DAMAGE-DESTROYED	OT-	0	0	0		INSTRUMENT RATED.
	DEPARTURE POINT		INTENDED DESTINATION				LAST ENROUTE STOP		
	BARANGIA,COLUMBIA		FT LAUDERDALE,FL				GREAT INAGUA,BAHAMAS		
	TYPE OF ACCIDENT						PHASE OF OPERATION		
	ENGINE FAILURE OR MALFUNCTION						IN FLIGHT: NORMAL CRUISE		
	DITCHING						LANDING: LEVEL OFF/TOUCHDOWN		
	PROBABLE CAUSE(S)								
	POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS								
	FACTOR(S)								
	MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER								
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE								
	EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER								
	REMARKS- DITCHED IN INTERNATIONAL WATERS.ACFT NOT RECOVERED.								

Full narrative is not available