NTSB Identification: FTW79FRG37

14 CFR Part 91 General Aviation Aircraft: SWEARINGEN SA226, registration: N5654M

FILE	DATE	LC	OCATION	AIRCRAFT	DATA		IJUR F			FLIGHT PURPOSE		PILOT DATA
3-1140	79/5/31 TIME - 1042		ARCOS,TX	SWEARINGEN N5654M DAMAGE-SUB		PX-	0	0	0	MISCELLANEOUS EXPERIMENTATION	46, 5	INE TRANSPORT, AGE 5300 TOTAL HOURS, 6 YPE, INSTRUMENT

NAME OF AIRPORT - SAN MARCOS MUNI
DEPARTURE POINT INTENDED DESTINATION
SAN MARCOS,TX LOCAL

PHASE OF OPERATION

TYPE OF ACCIDENT HARD LANDING LANDING: LEVEL OFF/TOUCHDOWN LANDING: ROLL

GEAR COLLAPSED

PROBABLE CAUSE(S)
PILOT IN COMMAND - IMPROPER OPERATION OF POWERPLANT & POWERPLANT CONTROLS
PILOT IN COMMAND - IMPROPER LEVEL OFF

FACTOR(S)

MISCELLANEOUS ACTS, CONDITIONS - OVERLOAD FAILURE REMARKS- FAA FLIGHT TEST PILOT AT CONTROLS.

Full narrative is not available