

NTSB Identification: DEN80FA016

14 CFR Part 91 General Aviation
 Aircraft: BEECH B60, registration: N6030S

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3993	79/12/28 TIME - 0930	HAYDEN, CO	BEECH B60 N6030S DAMAGE-DESTROYED	CR- 1 0 0 PX- 0 0 0 OT- 0 0 0	NONCOMMERCIAL CORP/EXEC	COMMERCIAL, FL. INSTR., AGE 57, 12800 TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - YAMPA VALLEY DEPARTURE POINT INTENDED DESTINATION DENVER, CO HAYDEN, CO TYPE OF ACCIDENT PHASE OF OPERATION COLLISION WITH GROUND/WATER: CONTROLLED LANDING: FINAL APPROACH PROBABLE CAUSE(S) PILOT IN COMMAND - IMPROPER IFR OPERATION FACTOR(S) WEATHER - LOW CEILING WEATHER - FOG WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT SKY CONDITION CEILING AT ACCIDENT SITE OBSCURATION 800 VISIBILITY AT ACCIDENT SITE PRECIPITATION AT ACCIDENT SITE ZERO NONE OBSTRUCTIONS TO VISION AT ACCIDENT SITE TEMPERATURE-F FOG 11 WIND VELOCITY-KNOTS TYPE OF WEATHER CONDITIONS CALM BELOW MINIMUMS TYPE OF FLIGHT PLAN IFR FIRE AFTER IMPACT REMARKS- VOR RWY 10 APCH. CRASHED 3.3NM NW OF ARPT AT 7200FT MSL.						

Full narrative is not available