

# NTSB Identification: LAX80FA005

14 CFR Part 91 General Aviation  
 Aircraft: SWEARINGEN SA26AT, registration: N65103

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3962	79/10/19 TIME - 2316	PALO ALTO,CA	SWEARINGEN SA26AT N65103 DAMAGE-DESTROYED	CR- 0 1 0 PX- 2 0 0 OT- 0 0 0	NONCOMMERCIAL BUSINESS	ATP, FLIGHT INSTR., AGE 33, 3331 TOTAL HOURS, 197 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - PALO ALTO		DEPARTURE POINT BAKERSFIELD,CA		INTENDED DESTINATION PALO ALTO,CA		
TYPE OF ACCIDENT BIRD STRIKE HARD LANDING		PROBABLE CAUSE(S) MISCELLANEOUS - FOREIGN MATERIAL AFFECTING NORMAL OPERATIONS PILOT IN COMMAND - IMPROPER RECOVERY FROM BOUNCED LANDING PILOT IN COMMAND - SPONTANEOUS-IMPROPER ACTION		PHASE OF OPERATION LANDING: LEVEL OFF/TOUCHDOWN LANDING: LEVEL OFF/TOUCHDOWN		
REMARKS- IFR CANCELLED,VFR LDG HARD,ABORTED LDG ROLL LEFT CRASHED INVERTED.L ENG BIRD INJECTION.7 ACFT DMGD						

Full narrative is not available