

NTSB Identification: LAX80FA064

14 CFR Part 91 General Aviation
 Aircraft: CESSNA 421B, registration: N59RZ

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-0396	80/3/14	NR.TUCSON,AZ	CESSNA 421B N59RZ DAMAGE-DESTROYED	CR- 1	0 0	0	MISCELLANEOUS TEST	ATP,FLIGHT INSTR., AGE 33, 9590 TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - RYAN FIELD DEPARTURE POINT INTENDED DESTINATION TUCSON,AZ LOCAL TYPE OF ACCIDENT PHASE OF OPERATION AIRFRAME FAILURE: IN FLIGHT IN FLIGHT: CLIMB TO CRUISE PROBABLE CAUSE(S) PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: INADEQUATE MAINTENANCE AND INSPECTION AIRFRAME - FLIGHT CONTROL SURFACES: ELEVATOR ASSEMBLY,ATTACHMENTS MISCELLANEOUS ACTS,CONDITIONS - MISSING MISCELLANEOUS ACTS,CONDITIONS - FLUTTER MISCELLANEOUS ACTS,CONDITIONS - OVERLOAD FAILURE FIRE AFTER IMPACT REMARKS- BAL WTS,PN 5034011-1 & -3,MISG FM ELEVS.ELEV PUSH-PULL TUBE RIVETS FAILED,OVRD.ELEV/STAB TWISTED.								

Full narrative is not available