NTSB Identification: IAD80FID08

14 CFR Part 135 Nonscheduled operation of AMICK AIRWAYS Aircraft: PIPER PA-31, registration: N77QC

FILE	DATE	LOCATION	AIRCRAFT DATA	INJUF F	S M		FLIGHT PURPOSE	PILOT DATA
3-0260	80/2/29 APPOMATTOX,VA TIME - 1030		PIPER PA-31 N77QC DAMAGE-DESTROYED		0	1	COMMERCIAL AIR TAXI-PASSG	ATP,FLIGHT INSTR., AGE 27, 3330 TOTAL HOURS, 1027 IN TYPE, INSTRUMENT RATED.
	DEPARTURE POINT INTENDED DESTINATION NORFOLK, VA ROANOKE, VA TYPE OF ACCIDENT ENGINE FAILURE OR MALFUNCTION COLLIDED WITH: FENCE, FENCEPOSTS PROBABLE CAUSE(S) PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARAT PILOT IN COMMAND - MISMANAGEMENT OF FUEL MISCELLANEOUS ACTS, CONDITIONS - FUEL EXHAUSTION FACTOR(S) POWERPLANT - POWERPLANT-INSTRUMENTS: FUEL QUANTI MISCELLANEOUS ACTS, CONDITIONS - IMPROPER ALIGNME COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAME EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPOR				TY GAUGE NT/ADJUSTMENT COUT-2 ENGINES			RATED.

Full narrative is not available