

## NTSB Identification: ANC80DA059

14 CFR Part 91 General Aviation

Aircraft: FAIRCHILD C-119L, registration: N90268

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-1523	80/7/5	KING SALMON,AK	FAIRCHILD C-119L	CR-	0	0	2	COMMERCIAL	ATP,FLIGHT INSTR., AGE
	TIME - 1208		N90268	PX-	0	0	0	CTR CARGO-D	28, 3568 TOTAL HOURS, 37
			DAMAGE-SUBSTANTIAL	OT-	0	0	0		IN TYPE, INSTRUMENT
									RATED.
		NAME OF AIRPORT - KING SALMON							
		DEPARTURE POINT		INTENDED DESTINATION					
		KENAI,AK		KING SALMON,AK					
		TYPE OF ACCIDENT				PHASE OF OPERATION			
		FIRE OR EXPLOSION: ON GROUND				LANDING: ROLL			
		PROBABLE CAUSE(S)							
		MISCELLANEOUS - UNDETERMINED							
		FACTOR(S)							
		MISCELLANEOUS ACTS,CONDITIONS - *ERROR-INVALID CODE*							
		FIRE AFTER IMPACT							
		REMARKS- NO.1 ENG FIRE WARNING LGT ILLUMINATED & FIRE OBSD IN NACELLE AREA.L WING TIP EXPLODED.							

Full narrative is not available