

NTSB Identification: DEN81FA060

14 CFR Part 135 Nonscheduled operation of AIR FREIGHT EX
 Aircraft: CESSNA T207, registration: N17464

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3416	81/8/21	NR.CASPER,WY	CESSNA T207 N17464 DAMAGE-DESTROYED	CR- 1 0 0 PX- 0 0 0 OT- 0 0 0	COMMERCIAL AIR TAXI-CARGO	AIRLINE TRANSPORT, AGE 28, 6939 TOTAL HOURS, 4673 IN TYPE, INSTRUMENT RATED.
		DEPARTURE POINT CASPER,WY	INTENDED DESTINATION ERIE,CO			
		TYPE OF ACCIDENT		PHASE OF OPERATION		
		ENGINE FAILURE OR MALFUNCTION		TAKEOFF: INITIAL CLIMB		
		COLLIDED WITH: TREES		LANDING: OTHER		
		PROBABLE CAUSE(S)				
		PERSONNEL - PRODUCTION-DESIGN-PERSONNEL: POOR/INADEQUATE DESIGN				
		POWERPLANT - FUEL SYSTEM: OTHER				
		MISCELLANEOUS ACTS,CONDITIONS - FUEL STARVATION				
		FACTOR(S)				
		PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING				
		MISCELLANEOUS ACTS,CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G.				
		MISCELLANEOUS ACTS,CONDITIONS - CARGO SHIFTED				
		PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE				
		EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND				
		REMARKS- VAPOR LOCK.APPROX 310LBS OVR MAX T/O WT.CARGO SHIFTED AT IMPACT CRUSHING PLT.				

Full narrative is not available