

ACCIDENT CLASSIFICATION									
UNIT 5 C.T.U. Boundary Bay		COM. WZC		PLACE Unknown.		DATE 14-7-44		TIME Unknownr	
A/C TYPE MITCHELL II		No. HD 319		CRASH CAT. NA Unknown		H.Q. FILE 1300-K219-1		S.E.	M.E.
						DAY		NIGHT	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES	SIGNAL			
Hannah, R.L.	GB	F/O	159853	Capt.	Missing	No.	DATE		
Reeve, J.W.C.	GB	P/O	1685944	NAV	Missing.	A158	14-7		
Johnston, D.	GB	P/O	1570510	A/B	Missing.	D 14 (REVISED)			
Waters, L.G.	GB	SGT	1387364	WAG	Missing.	No.	CHECKED		
						#1			
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Wright R-2600 P. 170657				INST.	NIGHT	ON TYPE		TOTAL	
29 S. 170627 Lost.						DUAL	SOLO	DUAL	SOLO
				42	132	28	15	231	1089
ACCIDENT CLASSIFICATION									

PURPOSE OF FLIGHT:

Navigation Exercise. Route 108

TECHNICAL OFFICER'S REPORT:

Unknown.

INK

NATURE OF ACCIDENT:

Unknown.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No. 2418

CAUSE: Obscure.

RECOMMENDATIONS: Nil

CONCLUSIONS OF A.I.B.

Agree that the cause is obscure.

CLASSIFICATION:

23. Not known.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: