

# NTSB Identification: Unknown

14 CFR Part 91 General Aviation  
Aircraft: CURTISS-WRT C-46F, registration: N1247N

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
6-0044	69/5/23 TIME - 0005	BARCELONA, VENZ, SA	CURTISS-WRT C-46F N1247N DAMAGE-DESTROYED	CR- 1 1 0 PX- 0 0 2 OT- 0 0 0	NONCOMMERCIAL CORP/EXEC	COMMERCIAL, AGE 28, 2670 TOTAL HOURS, 1820 IN TYPE, INSTRUMENT RATED.
	DEPARTURE POINT SURINAM	INTENDED DESTINATION CURACAO			LAST ENROUTE STOP GUYANA	
	TYPE OF ACCIDENT ENGINE FAILURE OR MALFUNCTION COLLISION WITH GROUND/WATER: CONTROLLED				PHASE OF OPERATION IN FLIGHT: NORMAL CRUISE LANDING: LEVEL OFF/TOUCHDOWN	
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND					
	REMARKS- INVESTIGATION UNDER JURISDICTION OF GOVT OF VENEZUELA.					

Full narrative is not available