

NTSB Identification: OAK70F0154

14 CFR Part 135 Nonscheduled operation of TRANS-ISLE AIR
Aircraft: DEHAVILAND 104-6A, registration: N669R

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-2849	69/11/3 TIME - 1527	KALAUPAPA,HAWA11	DEHAVILAND 104-6A N669R DAMAGE-SUBSTANTIAL	CR-	0	0	2	COMMERCIAL AIR TAXI-PASSG	AIRLINE TRANSPORT, AGE 38, 6559 TOTAL HOURS, 567 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - KALAUPAPA									
DEPARTURE POINT		INTENDED DESTINATION		LAST ENROUTE STOP					
HONOLULU,HAWAII		KALAUPAPA,HAWA11		KAANAPALI,HAWAII					
TYPE OF ACCIDENT				PHASE OF OPERATION					
UNDERSHOOT				LANDING: LEVEL OFF/TOUCHDOWN					
GEAR COLLAPSED				LANDING: LEVEL OFF/TOUCHDOWN					
PROBABLE CAUSE(S)									
PILOT IN COMMAND - MISJUDGED DISTANCE AND ALTITUDE									
PILOT IN COMMAND - FAILED TO INITIATE GO-AROUND									
FACTOR(S)									
WEATHER - DOWNDRAFT,UPDRAFTS									
MISCELLANEOUS ACTS,CONDITIONS - OVERLOAD FAILURE									
WEATHER BRIEFING - UNKNOWN/NOT REPORTED									
WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT									
SKY CONDITION				CEILING AT ACCIDENT SITE					
CLEAR				UNLIMITED					
VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE					
5 OR OVER(UNLIMITED)				NONE					
OBSTRUCTIONS TO VISION AT ACCIDENT SITE				RELATIVE BEARING OF WIND					
NONE				RIGHT QUARTERING HEAD WIND 023-067 DEGREES					
WIND DIRECTION-DEGREES				WIND VELOCITY-KNOTS					
85				15					
TYPE OF WEATHER CONDITIONS				TYPE OF FLIGHT PLAN					
VFR				NONE					
REMARKS- T/D IN ROCK AREA APRX 38FT SHORT OF RNWY.WIND GUSTING 20K.									

Full narrative is not available